

123 Sample Street, Houston, TX 77001
Phone: (713) 555-0199 | companyname@llc.com
License: TFS-55821 | EIN: 84-3957201

SERVICE DETAILS

Customer:	Bella's Italian Kitchen	Date:	Mar 22, 2026
Address:	456 Demo Ave, Houston, TX 77002	Technician:	Mike Johnson (#IKECA-4521)
		Next Due:	Apr 21, 2026

COMPONENTS CLEANED

Hood Canopy	CLEANED
Filters (Baffle/Mesh)	CLEANED
Plenum	CLEANED
Ductwork (Horizontal)	CLEANED
Ductwork (Vertical)	CLEANED
Access Panels	CLEANED
Exhaust Fan & Housing	CLEANED
Rooftop Discharge	CLEANED
Backsplash / Wall	CLEANED
Grease Gutters & Trays	CLEANED

COMPONENT CONDITIONS

Filters	GOOD
Ductwork	GOOD
Access Panels	GOOD
Fan Belts	GOOD
Hinge Kits	GOOD
Duct Seams/Joints	GOOD

AREAS NOT CLEANED / INACCESSIBLE

All areas accessible — no exclusions

DEFICIENCIES

No deficiencies found

BEFORE PHOTOS

IMAGE BEFORE CLEANING

Hood 1

IMAGE BEFORE CLEANING

Hood 2

IMAGE BEFORE CLEANING

Filters

IMAGE BEFORE CLEANING

Plenum

AFTER PHOTOS

IMAGE AFTER CLEANING

Hood 1

IMAGE AFTER CLEANING

Hood 2

IMAGE AFTER CLEANING

Filters

IMAGE AFTER CLEANING

Plenum

NFPA 96 CERTIFICATION

This kitchen exhaust system has been cleaned in accordance with NFPA 96 standards.

All accessible areas of the system have been cleaned to bare metal. Any areas not cleaned are noted above.

This report serves as the official record of service for compliance and insurance purposes.

Technician: Mike Johnson

Date: Mar 22, 2026

Customer: No manager available